

New Offences as the result of the introduction of Digital Tachographs

The offences listed at Annex A were introduced in April 2008 as the result of the introduction of Digital Tachographs. Since this date, VOSA have where applicable been issuing prohibitions for these offences.

The offences were included into the OCRS tables in April 2008 but with a 0 offence score. Since April 2008 operators would have seen the fact that an offence had been recorded in their OCRS reports.

VOSA have recently established a score for the new offences and have applied it to those offences where a 0 score had previously been recorded. This means that some operators will see a change to their OCRS score and possibly their banding. Where an operator has had their OCRS score re-calculated they will have been credited for any clear inspections in that time.

We have detected approximately 10,000 offences involving some 7,000 operators. This means that about 8% of GB operators may have seen a change to their Historic OCRS score as the result of this.

New Offences as the result of the introduction of Digital Tachographs

OFFENCE DESCRIPTION	OCRS Points
FAIL TO PERMIT COPY OF DATA S99ZA(2)(B) TA68	49
USE UNAUTHORISED DRIVER CARD A.14(4)(A) EC 3821/85	76
FAIL TO AMEND CHART/DRIVER CARD ART 15(2) 3821/85	29
USE DEFECT/EXPIRED DVR CARD A.14(4)(A) EC 3821/85	76
FAIL TO AMEND CHART/DRIVER CARD ART 15(2) 3821/85	29
FAIL TO ENTER PERIODS OF TIME ART 15(2)(A) 3821/85	29
NO START/END COUNTRY SYMBOL A15(5A) EC 3821/85	29
UNABLE TO PRINT ON REQUEST A14(1) EC 3821/85	29
USE RECORD SHEET/DRI.CARD TOO LONG A15(2)EC3821/85	49
USE DIRTY/DAMAGED RECORD/DRI.CARD A15(1) EC3821/85	31
FALSE ENTRY (REC/DOC) S99ZE(1)(A) (2) & (4) TA68	76
ALTERS RECORD/ENTRY S99ZE(1)(B), (2) & (4) TA68	76
FAIL TO MAKE RECD/ENTRY S99ZE(1)(D),(2)&(4) TA68	44
FALSIFY/SUPPRESS/DESTROY DATA ART15(8) EC3821/85	76
UNAUTHORISED DEVICE FITTED ART.15(8) EC3821/85	60
PRODUCE FALSE HARD COPY OF DATA S99ZE 3(D)&4 TA68	76
FAIL TO REC DATA ON TACHO/CARD S99ZE 3(F)&4 TA.68	44
FAIL TO PRINT/DETAIL (START) A.15(1)(A) EC 3821/85	29
FAIL TO PRINT/DETAIL (END) A.15(1)(B) EC 3821/85	29
TACHO REPAIR NOT IN ACCORD. ART12 ANNX1B EC3821/85	39
TACHO NOT SEALED IN ACCORD. ANNEX IB EC 3821/85	39
ALTERS RECORD/ENTRY S99ZE(1)(B), (2) & (4) TA68	76
EXCEED 4.5HRS DRIVING CONTRARY TO ART7 EC561/2006	40
EXCEED 10 HR DRIVE TO CONTRARY ART 6.1 EC561/2006	47
EXCEED 9 HR DRIVE CONTRARY ART 6.1 EC561/2006	47
EXCEED 56HR DRIVE CONTRARY ART 6.1 EC561/2006	37
EXCEED 90HR DRIVE CONTRARY ART 6.3 EC561/2006	37
INSUFF DAILY REST IN 24HR PERIOD ART8.2 EC561/2006	47
INSUFF DAILY REST DM IN 30H PERIOD A8.5 EC561/2006	47
INSUFF DAILY REST DM IN 24H PERIOD A8.5 EC561/2006	47
INSUFF WEEKLY REST PERIOD CONT ART8.6 EC 561/2006	42
FAIL TO USE TACHO RECORD/DVR.CARD A15.2 EC 3821/85	44
TACHO REPAIR NOT IN ACCORD. ART12 ANNX1 EC3821/85	39
TACHO NOT SEALED IN ACCORD. ANNEX I EC 3821/85	39
FAIL PRODUCE CHARTS/D.CARD/P-OUT A15.7 EC 3821/85	49
FAIL TO PRODUCE DOCUMENTS S99ZA(1)(C) TA68	49